

Figure D-13. The TRA-13 Sewage Leach Pond cover looking east (PN02274-1-4).




Figure D-14. Anthill located on the northern portion of the TRA-13 Sewage Leach Pond cover (PN02274-1-5).




Figure D-15. Comprehensive Environmental Response, Compensation, and Liability Act sign at TRA 15 Hot Waste Tanks 2, 3, and 4 (PN02274-2-4).



Figure D-16. The TRA-15 Hot Waste Tanks 2, 3, and 4 looking south (PN02274-2-5).



Figure D-17. Comprehensive Environmental Response, Compensation, and Liability Act sign at TRA-19 Tanks 1 and 4 at TRA-630, posted on exterior of building controlling access to the site (PN02274-2-6).



Figure D-18. The TRA-Y Brass Cap Site (PN02274-2-0).